

## **THE FOLLOWING INFORMATION IS IN ADDITION TO THE HOME INSPECTION AND IS USED IN CONJUNCTION WITH THE INSPECTION REPORT.**

### **LIMITATIONS OF STRUCTURE INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Structural components concealed behind finished surfaces could not be inspected.
- Only a representative sampling of visible structural components were inspected.
- Furniture and/or storage restricted access to some structural components.
- Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a home inspection.

### **LIMITATIONS OF ROOFING INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Not all of the underside of the roof sheathing is inspected for evidence of leaks.
- Evidence of prior leaks may be disguised by interior finishes.
- Estimates of remaining roof life are approximations only and do not preclude the possibility of leakage. Leakage can develop at any time and may depend on rain intensity, wind direction, ice build up, and other factors.
- Antennae, chimney/flue interiors which are not readily accessible are not inspected and could require repair.
- Roof inspection may be limited by access, condition, weather, or other safety concerns.

### **LIMITATIONS OF EXTERIOR INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- A representative sample of exterior components was inspected rather than every occurrence of components.
- The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards.
- Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawalls, break-walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report.

### **LIMITATIONS OF ELECTRICAL INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Electrical components concealed behind finished surfaces are not inspected.
- Only a representative sampling of outlets and light fixtures were tested.
- Furniture and/or storage restricted access to some electrical components which may not be inspected.
- The inspection does not include remote control devices, alarm systems and components, low voltage wiring, systems, and components, ancillary wiring, systems, and other components which are not part of the primary electrical power distribution system.

### **LIMITATIONS OF HEATING INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- The adequacy of heat supply or distribution balance is not inspected.
- The interior of flues or chimneys which are not readily accessible are not inspected.
- The furnace heat exchanger, humidifier, or dehumidifier, and electronic air filters are not inspected.
- Solar space heating equipment/systems are not inspected.

## **LIMITATIONS OF COOLING / HEAT PUMPS INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Window mounted air conditioning units are not inspected.
- The cooling supply adequacy or distribution balance are not inspected.

## **LIMITATIONS OF INSULATION / VENTILATION INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Insulation/ventilation type and levels in concealed areas are not inspected. Insulation and vapor barriers are not disturbed and no destructive tests (such as cutting openings in walls to look for insulation) are performed.
- Potentially hazardous materials such as Asbestos and Urea Formaldehyde Foam Insulation (UFFI) cannot be positively identified without a detailed inspection and laboratory analysis. This is beyond the scope of the inspection.
- An analysis of indoor air quality is not part of our inspection unless explicitly contracted-for and discussed in this or a separate report.
- Any estimates of insulation R values or depths are rough average values.

## **LIMITATIONS OF PLUMBING INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Portions of the plumbing system concealed by finishes and/or storage (below sinks, etc.), below the structure, or beneath the ground surface are not inspected.
- Water quantity and water quality are not tested unless explicitly contracted-for and discussed in this or a separate report.
- Clothes washing machine connections are not inspected.
- Interiors of flues or chimneys which are not readily accessible are not inspected.
- Water conditioning systems, solar water heaters, fire and lawn sprinkler systems, and private waste disposal systems are not inspected unless explicitly contracted-for and discussed in this or a separate report.

## **LIMITATIONS OF INTERIOR INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Furniture, storage, appliances and/or wall hangings are not moved to permit inspection and may block defects.
- Carpeting, window treatments, central vacuum systems, household appliances, recreational facilities, paint, wallpaper, and other finish treatments are not inspected.

## **LIMITATIONS OF APPLIANCES INSPECTION**

---

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Thermostats, timers and other specialized features and controls are not tested.
- The temperature calibration, functionality of timers, effectiveness, efficiency and overall performance of appliances is outside the scope of this inspection.



## REMARKS

### SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost. Patios that have settled towards the structure should be corrected or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements. City walks are not part of the inspection.

### EXTERIOR WOOD SURFACES

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts which are buried in the ground and made of untreated wood will become damaged quickly. Rust/corrosion resistant hardware should be used on exterior areas. Types of hardware can not always be determined. Wood surfaces that are not painted or stained should be treated with a water sealer. Deck/balcony footings are not part on the inspection. If a permit was not taken for the deck/balcony, recommend having evaluated for proper construction by a licensed contractor.

### GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Soil shall be approximately 6" below the bottom sill (in areas where homes are sided close to ground level, this can not be achieved) and should not touch wood/siding surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation can trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Landscaping such as rock and wood chips can deter the visual inspection of landscape grading..

### ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement. This means keeping gutters cleaned out, extending downspouts, installing splashblocks, and building up the grade so that roof and surface water is diverted away from the building.

### WINDOW WELLS

The amount of water which enters a window well from falling rain is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

### RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Conditions can often be improved by excavating a trench behind the retaining wall and filling it with coarse gravel. Drain holes through the wall will then be able to relieve the water pressure. Drain hole are not always present or visible. Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope.

### RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches/decks over 30". Balusters for porches, balconies, decks, and stairs should be close enough to assure children cannot squeeze through.



## REMARKS

Valleys and flashings that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

Tar and rock/built-up roofs are a type of covering on a pitched roof that requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS
<i>Asphalt/fiberglass Shingles*</i>	15-20 years	Used on nearly 80% of all residential roofs; requires little maintenance
<i>Asphalt/fiberglass Multi-Thickness Shingles*</i>	20-30 years	Heavier and more durable than regular asphalt shingles
<i>Asphalt/fiberglass Interlocking Shingles*</i>	15-25 years	Especially good in high-wind areas
<i>Asphalt Rolls</i>	10 years	Used on low slope roofs
<i>Built-up Roofing</i>	10-20 years	Used on low slope roofs; 2 to 3 times as costly as asphalt shingles
<i>Wood Shingles*</i>	10-40 years <sup>1</sup>	Treat with preservative every 5 years to prevent decay
<i>Clay Tiles*</i> <i>Cement Tiles*</i>	20 + years 20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base
<i>Slate Shingles*</i>	30-100 years <sup>2</sup>	Extremely durable, but brittle and expensive
<i>Asbestos Cement Shingles*</i>	30-75 years	Durable, but brittle and difficult to repair
<i>Metal Roofing</i>	15-40 + years	Comes in sheets & shingles; should be well grounded for protection from lightning; certain metals must be painted
<i>Single Ply Membrane</i>	15-25 years (mfr's claim)	New material; not yet passed test of time
<i>Polyurethane with Elastomeric Coating</i>	5-10 years <sup>1</sup>	Used on low slope roofs.

\* Not recommended for use on low slope roof

<sup>1</sup> Depending on local conditions and proper installation

<sup>2</sup> Depending on quality of slate

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles. One layer of shingles is recommended.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.

The underside and attaching of the shingles can not be determined during an inspection. Shingles are not inspected to verify proper sealing. Visible indications of wind damage is completed at the time of inspection only.



## REMARKS

### CHIMNEYS

Chimneys built of masonry will eventually need tuckpointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimney's condition. The flashing around the chimney may need resealing and should be inspected seasonally. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels.

Unlined chimney's should be re-evaluated by a chimney technician.

**Have flue cleaned and re-evaluated.** The flue lining is covered with soot or creosote, or is not visible and no representation can be made as to the condition. *(If marked on your report)*

### NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, cleanout not accessible, etc.

### CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. These are not installed on all homes. Recommend installed during re-shingling.

### GUTTERS AND DOWNSPOUTS

This is an extremely important element in basement dampness control. Keep gutters clean and downspout extensions in place (4' or more). Shortly after a rain or thaw in winter, look for leaks at seams in the gutters. These can be re-caulked before they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added. Gutters need to be cleaned seasonally.

### SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. (EIFS) This type of siding is a synthetic stucco type and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also.

Metal siding will dent and scratch. Oxidation is a normal reaction. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted if properly done.

Vinyl siding can crack and chip easily. Be careful when working near siding. Vinyl siding can shift and cause gapping. Waiving in vinyl siding is normal.

### DOORS AND WINDOWS

These can waste an enormous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve as needed. The exposed side of exterior doors needs to be painted or properly stained and varnished to prevent discoloring and delaminating. Weatherstripping is a must to prevent drafts. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat can indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with). Recommend removing interior screens and open blinds to allow air circulation at the windows. As inspectors, we can not determine how drafty a house will be.

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, or interior moisture from baths or laundry. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.



## ELECTRICAL/A/C - HEAT PUMP

### REMARKS

#### ELECTRICAL

Exterior outlets are checked if readily visible. Proper routing of the wiring can not be determined.

#### A/C COMPRESSORS

They should not become overgrown with foliage. Clearance requirements vary, but one foot on all sides should be considered minimal with up four to six feet of air discharge desirable. If a clothes dryer vent is within five to ten feet, monitor to ensure the AC unit stays clean. The lint will quickly reduce the efficiency of the A/C unit. AC cooling fins should be cleaned seasonally. Level the AC unit as needed. Some AC units are not required to be covered during winter months. Replace the AC line insulation as needed. Recommend using the rubberized line insulation designed for exterior use.



## GARAGE

### REMARKS

#### OVERHEAD DOOR OPENERS

It is recommended that extension cord wiring to an automatic door opener be removed and an outlet should be installed by the opener. Openers that do not have a **safety reverse** are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If an electric sensor is present, it should be tested occasionally to ensure it is working. We recommend inspecting the door hardware to include cables on a regular basis. Door springs will break and cable will fray at any time. The doors are not designed to be air tight. Gaps and drafting is normal.

#### BURNERS

Any appliance such as a water heater, furnace, etc. should have the flame a minimum of 18" above the floor. Any open flame less than 18" from the floor is a potential safety hazard. The appliance should also be protected from vehicle damage. Many garage heaters are added after the home is built. We recommend verifying that a permit was taken and the unit is properly installed. If not, we recommend having a HVAC tech or electrician verify proper installation. Inspectors are not required to operate heaters that are shut down and not being used.

#### FIRE WALLS

A fire wall in the garage slows a fire from spreading into the home. Codes for these have changed over the years. We recommend contacting the local city/area inspector to verify that standards are met. The type of home loan can require firewalls to be installed.

Garage attic stairs require an opening be cut into the garage ceiling. If the ceiling is part of the firewall, a fire resistant material should be installed on the underside of the steps.

#### SILL PLATES

Garage sill plates should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting. Not all sill plates are visible due to items and wall coverings in a garage.



## **KITCHEN REMARKS**

### **WALLS AND CEILING**

Cracks and open tape joints can and do happen. Staining at the walls and ceiling can occur due to the amount of moisture in a kitchen.

### **CABINETS AND COUNTER TOPS**

Cabinets will have normal wear. Doors and hinges will need adjusting. Areas under the kitchen sink are normally filled with personal belongings and the condition can not be verified. Countertops are inspected for serviceability and not for wear and tear.

### **FLOORING**

Floor covering in a kitchen vary in material used. Tile flooring can crack. Repair tile floor grouting as needed. Many times rugs will cover flooring. These areas will not be inspected. Inspectors are concerned with the floor and not the floor covering.

### **APPLIANCES**

(If report indicated appliances were operated, the following applies) Dishwashers are tested to see if the motor operates. It does not determine if the unit cleans properly. Rusting of the racks is a normal occurrence and is not required to be documented. Disposal wiring is not inspected per code. Stoves are tested to see that burners are working and oven gets hot. Timer and controls are not tested. Refrigerators are not tested for proper operation. If on, we verify that the unit is cool. Microwaves are not operated. Exhaust fans are operated. We do not determine where they vent. No representation is made to continued life expectancy of any appliance.

### **WINDOWS**

A representative number of windows are inspected. Windows can be blocked from access due to furniture and other personal items.

### **AN INSPECTION VERSUS A WARRANTY**

A home inspection is just what the name indicates, an inspection of a home...usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspector's ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home and to report it accurately. The report that is issued is an opinion as to the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. It is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.



## BATHROOM(S)

# REMARKS

### SHOWER/TUB

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use. Metal tub chips are considered normal wear and are not documented as a concern. Surface cracking of a fiberglass shower/tub can be covered with soap scum and mats. The inspection is for operation and does not cover general wear.

### CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through. Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations. Damage behind the tiles can not be determined.

### EXHAUST FANS

Exhaust fans were not required in earlier built homes. Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting into a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem. Many times the venting can not be determined due to limited attic access and insulation.

**SLOW DRAINS** on sinks, tubs, and showers are usually due to build up of hair and soap scum. Slow drains can happen any time after the home inspection. Most sink drain popups can be easily removed for cleaning. Some tubs have a spring attached to the closing lever that acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. *Don't use a caustic cleaner.*

### SAFETY HAZARDS

Typical safety hazards found in bathrooms are outlets with open grounds or reverse polarity near water. Proper wiring and replacing these outlets with G.F.C.I.'s are recommended.

### WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tubs and spas are not inspected. Recommend adding a pump access panel where needed.

The logo features a stylized house icon with a semi-circle at the base of the roofline, positioned to the left of the word "INTERIOR" in a grey rectangular box. Below this, the words "ROOMS REMARKS" are written in a larger, bold, black sans-serif font.

**INTERIOR**  
**ROOMS REMARKS**

#### **DOOR STOPS**

Recommend installing door stops on all doors. Broken or missing door stops can result in door knobs breaking through drywall or plaster. Replace/install as needed.

#### **CLOSET GUIDES**

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors. General wear is expected.

#### **COLD AIR RETURNS**

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return. Older homes have limited numbers of cold air returns.

#### **PLASTER ON WOOD LATH**

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Cracks and open tape joints can happen. Staining can occur in closets due to a lack of air movement. Closets are usually full and inspections in the area is limited to what is visible.

#### **WOOD FLOORING**

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild bleaching agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done safely only once or twice in the life of the floor. The inspection covers the structure of the floor and not the condition of the floor covering. Sun and rugs can discolor the flooring.

#### **NAIL POPS**

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

#### **CARPETING**

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

#### **ASBESTOS AND OTHER HAZARDS**

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing. If there is reason to suspect that asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. This is the buyer's responsibility. Detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.



INTERIOR

# REMARKS

## WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house.

See comments regarding caulking doors and windows.

## FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire. Most chimney's have limited access and can not be fully inspected.

Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform to most building codes.

During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner either because of stoppage at the firebox, a defective damper or lack of access from the roof. Chimney caps are not removed during inspections.

## WOODBURNERS

Once installed, it can be difficult to determine proper clearances for woodburning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that it was installed by a professional contractor. If information is not available we recommend having a contractor evaluate for proper installation.

## VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 300 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should ideally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Evidence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been or is blocked or inadequate. Attic venting is a visual inspection by inspectors.

## INSULATION

The recommended insulation in the attic area is R-38, approximately 12". Insulation does settle over time. Areas that are blocked or are not visible can not be evaluated for proper insulation.

**NOTE: Ice damming can not be determined.**

## SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

## VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

## SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

## INSULATED GLASS

Broken seal in thermopane/insulated windows are not always visible nor detectible due to humidity and temperature changes during the day. Other factors such as window covering, dirty windows, and lack of accessibility, personal property placed in front of the windows all affect the view of the windows at the time of the inspection. Seal can leak at any time.



# REMARKS

## BASEMENT

Many basements have cracks or possible leaks. Most block basements have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If the wall containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements that have been freshly painted or tuckpointed should be monitored for movement and leaks. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement wall can become expensive. Future basement seepage can not be determined.

## FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished, or basement storage makes areas inaccessible. **No representation is made as to the condition of these walls.**

**MONITOR** indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be sealed and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

**HAVE EVALUATED** We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

## VAPOR BARRIER

Floors that are dirt or gravel are recommended to be covered with a vapor barrier.

## MOISTURE PRESENT

Basement dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet. This can not always be obtained due to the siding being close to ground level.

Expensive solutions to basement dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. **No representation is made to future moisture that may appear.**

## PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

## DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

## BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces, but may not be required.



## REMARKS

### CRAWL SPACES

Crawl spaces are shallow spaces between the first level floor joist and the ground. Access to this area may be from the inside, outside or not accessible at all. Ductwork, plumbing, and electrical may be installed in the space in which access may be necessary. The floor of the crawl space may be covered with concrete, gravel, or may be the original soil. A vapor barrier may be a sheet of plastic or tar paper and installed over or under this material. The vapor barrier will deter the moisture from the earth from escaping into the crawl space. Ventilation is also important to control excess moisture buildup. Vents may be located on the outside of the house and are normally kept open in the summer and closed for the winter (where freezing may occur).

The basement/crawl space many times has limited visible areas due to insulation and crawl space clearances. Every attempt is made to determine the condition.

### HAVE EVALUATED

If marked in the report, we recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

### MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be sealed and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.



PLUMBING

## REMARKS

### WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

### SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system.

### WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 5 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house later as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

### HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized or during cold weather. Be sure to remove all hoses prior to winter.

### WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need not be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

### WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened or if the softener operates.

### PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valve's handle. Caution: very hot water will be discharged. If no water comes out, the valve is defective and must be replaced. This is not tested during an inspection.

### SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, hose faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be repacked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year. Shut off valve can and will have corrosion and staining. During an inspection, our concern is for leaking valves.

### POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

***MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.***

### CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.



# REMARKS

**HEATING AND AIR CONDITIONING** units have limited lives. Normal lives are:

GAS-FIRED HOT AIR.....	13-25 years
OIL-FIRED HOT AIR.....	13-30 years
CAST IRON BOILER.....	20-50 years
(Hot water or steam)	or more
STEEL BOILER.....	20-40 years
(Hot water or steam)	or more
COPPER BOILER.....	10-20 years
(Hot water or steam)	
CIRCULATING PUMP (Hot water).....	7-15 years
AIR CONDITIONING COMPRESSOR...	7-15 years
HEAT PUMP.....	7-15 years

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing **Caution: do not add water to a hot boiler!**

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor.

Oil-fired furnaces and boilers should be serviced by a professional each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. **During a visual inspection it is not possible to determine if the humidifier is working.**

**Have HVAC technician examine** (*If marked in the inspection report*) A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

**Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.**

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

**CO Test** This is not part of a non-technical inspection. CO alarms are recommended and installed per the requirements noted with the alarm.


**Combustible Gas Detector** If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.



## REMARKS

Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We recommend that ground fault circuit interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. G.F.C.I.'s are recommended by all outlets located near water, outside outlets, or garage outlets. Pool outlets should also be protected with a G.F.C.I.

See diagram below:



If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when needed.

Knob and tube wiring found in older homes should be checked by an electrician to insure that the wire cover is in good condition. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

**Federal Pacific Stab-Lok® Electrical panels may be unsafe. See [www.google.com](http://www.google.com) (Federal Pacific)**

**Aluminum wiring in general lighting circuits has a history of over heating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.**

### ARC FAULTS

In some areas arc faults are required in new homes, starting in 2002 and these control outlets in the bedrooms. Newer standards require them in most rooms.

### REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires of a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When these wires are switched, this is called "reverse polarity."

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp services. Larger homes or all electric homes will likely have a 200 amp service.

Main service wiring may be protected by one or more circuit breakers or fuses. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

### COOLING

Testing A/C System and Heat Pump- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65° for the past 24 hours to run in cooling mode.

Temperature differential, between 14°-22°, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

## PREVENTIVE MAINTENANCE TIPS

- I. **FOUNDATION & MASONRY:** *Basements, Exterior Walls:* To prevent seepage and condensation problems.
  - a. Check basement for dampness & leakage after wet weather.
  - b. Check chimneys, deteriorated chimney caps, loose and missing mortar.
  - c. Maintain grading sloped away from foundation walls.
  
- II. **ROOFS & GUTTERS:** To prevent roof leaks, condensation, seepage and decay problems.
  - a. Check for damaged, loose or missing shingles, blisters.
  - b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation. Cut back tree limbs.
  - c. Check flashings around roof stacks, vents, skylights, chimneys, as sources of leakage. Check vents, louvers and chimneys for birds nests, squirrels, insects.
  - d. Check fascias and soffits for paint flaking, leakage & decay.
  
- III. **EXTERIOR WALLS:** To prevent paint failure, decay and moisture penetration problems.
  - a. Check painted surface for paint flaking or paint failure. Cut back shrubs.
  - b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.
  
- IV. **DOORS AND WINDOWS:** To prevent air and weather penetration problems.
  - a. Check caulking for decay around doors, windows, corner boards, joints. Recaulk and weatherstrip as needed. Check glazing, putty around windows.
  
- V. **ELECTRICAL:** For safe electrical performance, mark & label each circuit.
  - a. Trip circuit breakers every six months and ground fault circuit interrupters (G.F.C.I.) monthly.
  - b. Check condition of lamp cords, extension cords & plugs. Replace at first sign of wear & damage.
  - c. Check exposed wiring & cable for wear or damage.
  - d. If you experience slight tingling shock from handling or touching any appliance, disconnect the appliance & have it repaired. If lights flicker or dim, or if appliances go on and off unnecessarily, call a licensed electrician.
  
- VI. **PLUMBING:** For preventive maintenance.
  - a. Drain exterior water lines, hose bibs, sprinklers, pool equipment in the fall.
  - b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
  - c. Have septic tank cleaned every 2 years.
  
- VII. **HEATING & COOLING:** For comfort, efficiency, energy conservation and safety.
  - a. Change or clean furnace filters, air condition filters, electronic filters as needed.
  - b. Clean and service humidifier. Check periodically and annually.
  - c. Have oil burning equipment serviced annually.
  
- VIII. **INTERIOR:** General house maintenance.
  - a. Check bathroom tile joints, tub grouting & caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors & ceilings below.
  - b. Close crawl vents in winter and open in summer.
  - c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.
  
- IX. **Know the location of:**
  - Main water shutoff valve.
  - Main electrical disconnect or breaker.
  - Main emergency shutoff switch for the heating system.